



WARNING



Your Oden
GEN2/-
GEN3.5 Filler
Electronics
have expired




Oden GEN2 and GEN3.5 electronics components have been obsolete for years. Oden no longer uses proprietary control electronic components. Oden has a variety of engineered upgrade programs to allow continued use of your GEN2 and GEN3.5 fillers.

1. PLC and HMI upgrades.
2. Full machine refurbishments to Oden non-proprietary GEN6 electronics.
3. Trade in your obsolete filler for a new GEN6 Oden filling system

Act now!
Don't wait
for a
system failure.


ACT NOW: FACTORY REFURBISHMENT

Before



After


Before



After

ACT NOW: GEN6 ELECTRONICS UPGRADE

Before



After

ACT NOW: TRADE IN FOR NEW MACHINE

Before



After

Act now to prevent extended downtime in the event of a GEN2/GEN3.5 electronics component failure.

Take time now to talk with our technical salesman about your GEN2/GEN3.5 machine.